

# CORNER RECORD

COUNTY OF ~~INYO~~ **MONO** T. **9N** R. **22E** MERIDIAN CALIFORNIA  
 CORNER TYPE: GOV'T. CORNER ☒ MEANDER ☐ RANCHO ☐ CONTROL ☐ OTHER ☐  
 CORNER IDENTIFICATION - DATE OF VISIT **21 AUG 1975**

26	25
35	36

Observed and photographed by M Allstead  
 1/4 W.C.  
 Witness Corner **25**  
**36**

CORNER - LEFT AS FOUND ☐ FOUND AND TAGGED ☐ REESTABLISHED OBLITERATED CORNER ☐ REBUILT ☐

PHYSICAL DESCRIPTION OF CORNER FOUND: EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

Roll #2 Frame #7 - Close up of cap with lettering facing West  
 Roll #2 Frame #8 - From 10± ft S of corner looking North  
 toward Ashurst Ranch houses along canal

**FD. W.C. ON WEST BANK OF RIVER CANAL ABOUT 20'± N. OF 1.5" DIA. PIPE THAT CROSSES CANAL & 120'± S. OF ANOTHER PIPE CROSS-**

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED


**ING CANAL. THE W.C. IS ON EDGE OF CANAL BANK, A BRASS CAP MOUNTED ON A 1" PIPE 1.2'± ABOVE GROUND. CAP IS STAMPED "U.S. GEN. LAND OFFICE SURVEY 1941" 1 325. BUILT ROCK PILE 1.5'± DIA. GROUND POINT & WHITE 536 FLAGGED ON ORANGE WHITE METAL FENCE.**

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST ☐ SECOND ☐ THIRD ☐

STATIONS USED: NGS (USC & GS) ☐ STATE ☐ COUNTY ☐ OTHER ☐ STATION \_\_\_\_\_ STATION \_\_\_\_\_

ZONE \_\_\_\_\_ ELEVATION \_\_\_\_\_ NORTHINGS (Y) \_\_\_\_\_ EASTINGS (X) \_\_\_\_\_

SKETCH: (Include reference tie or witness points, remarks and topo of area)



## SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON **8-21-75** **7-25 1978**

SIGNED: *James C. Hunsape*

L.S. or P.C.E. No.: **4468**

SEAL

## COUNTY SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS RECEIVED \_\_\_\_\_ 19\_\_\_\_ AND EXAMINED AND FILED \_\_\_\_\_ 19\_\_\_\_

BY: \_\_\_\_\_

TITLE: \_\_\_\_\_

DOCUMENT No. **9N22-25-3**

STATEMENT ON BACK OF SHEET

YES ☐ NO ☐